

Commissioner for Patents United States Patent and Trademark Office P.O. Box 1450 Alexandria, VA 22313-1450 www.uspto.gov

Date Mailed : August 25, 2006

Patent No. Inventor

: 7,054,460 B2 : Rombach et al

Patent Issued: August 14, 2006

Title

: MICROMACHINED MAGNETICALLY BALANCED MEMBRANE

ACTUATOR

Docket No.

: 45900-000663

Re: Request for Certificate of Correction

Consideration has been given your request for the issuance of a certificate of correction for the above-identified patent under the provisions of Rule 1.322.

Inspection of the file of the application for the patent reveals that column 8, line 58 of the specification is/are printed in accordance with the record in the Patent and Trademark Office, as passed to issue by the examiner. There being no fault on the part of the Patent and Trademark Office, it has no authority to issue a certificate of correction under the provision of 1.322.

In view of the foregoing, your request for certificate of correction is hereby denied. However, further consideration will be given these matters, upon receipt of a request for certificate of correction under the provisions of 1.323, accompanied by the appropriate fee which is presently \$100.

A certificate of correction will be issued to correct the error(s) noted in your request.

Future correspondence concerning this matter should be filed and directed to Decisions & Certificates of Correction Branch.

Commissioner of Patents P.O. Box 1450

Alexandria, VA 22313-1450

Attn: Certificates of Correction Branch

David Irvine Cecilia Newman, Supervisor Decisions & Certificates of Correction Branch 703/308-9590 or 703/305-4362 (Fax 571/270-9806)

John A. Castellano Harness Dickey & Pierce PLC 11730 Plaza America Drive – Suite 600 Reston, Va. 20190

CBN/ di

PTQ/SB/44 (04-04) Approved for use through 04/30/2007, OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE ct of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

SEX NO. 09464897

DATED: August 14, 2006

INVENTOR(S): Pirmin ROMBACH et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

We have found the following errors in the patent: Column 7

Claim 1, line 51: "magnetic material" should be replaced by –soft magnetic material-.

Claim 9, line 14: "of" should be replaced by -or-.

Claim 10, line 17: the second occurance of "of" should be replaced by -on-.

COLUMNA Claim 13, line 27: "according to claim 6" should be replaced by -according to claim 3-; line 27, remove the term

colomn8

Claim 13 line 29: "of Ag of any combination" should be replaced by -or Ag or any combination thereof-

Claim 17, line 39: of cellular should be replaced by or cellular.

Claim 20, line 58: -to-should be added after "according".

MAILING ADDRESS OF SENDER:

Harness, Dickey & Pierce, P.L.C. 11730 Plaza America Drive, Suite 600 Reston, VA 20190

PATENT NO. 7,054,460

No. of additional copies



This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application from to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commence, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Cartificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

16.16 TUNP